






RADAS






Ax90 	Bx90 $\Phi 15 \times 11$ 	Cx14 $\Phi 8 \times 40$ 	Dx10 $M5 \times 40$ 	Ex4SET  DR DL CR CL
Fx1  400	Gx3 $M4 \times 18$ 	Hx40 $M3.5 \times 14$ 	Jx16 $M3.5 \times 35$ 	Kx6 
Lx2 	Mx8 	Nx90 		


1

Ax28




2

Ax33




3

A×8	E×4SET	H×8
		
	CR CL CL CL 300	M3.5×14






4




A×11	E×4SET	H×8
		
	CR CL CL CL 300	M3.5×14




5






6



7





8







6


9




10



11




12






13

$B \times 4$ $\Phi 15 \times 11$	$C \times 2$ $\Phi 8 \times 40$
	
$N \times 4$ 	






14





$B \times 18$ $\Phi 15 \times 11$	$C \times 4$ $\Phi 8 \times 40$
	
$N \times 18$ 	



15







16




17

Bx12 Φ 15*11 	E x 3SET 	G x 3 M4*18 
H x 12 M3. 5*14 	J x 12 M3. 5*35 	N x 12 








19




20




21



22



23



24

