
























POHOS

| | | | | | |
|--|---|--|---|---|---|
| A  2 x | B  M6X50mm 8 x | C  M6X40mm 6 x | D  M6X30mm 4 x | E  M6X25mm 8 x | F  M6X12mm 2 x |
|--|---|--|---|---|---|


| | | |
|--|---|--|
| 1  x2 | 2  x2 | 3  x2 |
| 4  x2 | 5  x2 | 6  x2 |

| | | | | | |
|--|---|---|--|---|--|
| <p>G</p>  <p>ST5X50mm 10 x</p> | <p>H</p>  <p>ST4X12mm 4 x</p> | <p>I</p>  <p>M6X20X10mm 5 x</p> | <p>J</p>  <p>8 x</p> | <p>K</p>  <p>12 x</p> | |
|--|---|---|--|---|--|



| | | | | | |
|--|--|--|--|--|--|
| | | | | | |
|--|--|--|--|--|--|

13



14

