




FRISBO 80 D 3S BB



KUH.10225	815x500x16
KUH.10226	815x500x16
KUH.60032 x2	713x390x2,5
KUH.90133 x2	767x100x16
KUH.90134 x2	767x100x16
KUH.90040	799x95x16









8x30mm	6,4 x 50mm			6.5x48x16
A	B	E1	E9	F2
8	8	8	2	4
L1=680mm		4.0x45mm	3.0x20mm	4.0x35mm
L1	O	P4	P7	R3
1	1	2	10-15	4







1

6.5x48x16 F2 4	ø8x30mm A 8
----------------------	-------------------




2

6,4 x 50mm		
		
B	O	E1
4	1	4






3






6,4 x 50mm		
		
B	O	E1
4	1	4

4





5






6

4.0x45mm  P4 2	 E9 2
---	---





7


4.0x35mm  R3 4




1

								
2	2	4	4	4	8	16	4	4


1.




2.



3.







4.



x2








2

11D	11C	11E	P11	P5	11G	J5
1	1	2	4	8	2	2



3



		
11A	M3	P1
3	12	12



4



3



KUH.71169

KUH.71170

KUH.71170