



FRISBO 50 ZL 1F BB




KUH.40006



KUH.10259	815x500x16
KUH.10260	815x500x16
KUH.40006	467x485x16
KUH.90005	467x63x16
KUH.90008	467x130x16
KUH.90016	499x95x16









±8x30mm	6,4 x 50mm
A	B
8	8

E1	E9	F2	HG	O	P4	P5
8	2	4	2	1	2	4






1

6.5x48x16  F2 4	ø8x30mm  A 8
---	--




2

6,4 x 50mm		
		
B	O	E1
4	1	4





3




6,4 x 50mm		
		
B	O	E1
4	1	4

4

4.0x45mm  P4 2	 E9 2
--	--




5




		713x496

50 ZL 1F BB



50 G-72 1F




L=256mm	±7/2mm
S	J5
1	2



KUH.71150	713x496x16
-----------	------------

		713x496

50 ZL 1F BB



50 G-72 1F







L=256mm S 1	±7/2mm J5 2
----------------------------------	----------------------------------

KUH.71150	713x496x16
-----------	------------




1

50 ZL 1F BB

±35/0mm [CD] HG 2	±3.5x13mm P5 4	±7/2mm J5 2
----------------------------	----------------------	-------------------





2



KUH.71150

KUH.71150



3

50 G-72 1F

