




FRISBO 30 G 90 1F




KUH.30012
KUH.40018











KUH.10013 x2	900x290x16
KUH.30012 x3	266x250x16
KUH.40018 x2	267x276x16
KUH.60293	896x285x2,5

 †8x30mm A 8	 6,4 x 50mm B 8	 E1 8	 †35/0mm HG 2	 †3.5x13mm P5 4	 †3.0x20mm P7 8-10	 †4.0x30mm P8 4
 J 12	 K 2	 O 1				







1

 +8x30mm A	 +4.0x30mm P8	 K
8	4	2




2


6,4 x 50mm






3






6,4 x 50mm













4






5





6








7








8





896x296







L=160mm	+7/2mm
	
S	J5
1	2

KUH.71154	896x296x16
-----------	------------

2

$\pm 35/0\text{mm}$ [CD] HG 2	$\pm 3.5 \times 13\text{mm}$ P5 4	$\pm 7/2\text{mm}$ J5 2
-------------------------------------	---	-------------------------------



3

L=160mm S 1

