



LUSY



160,180x200
Wx900x2100 mm




	W (mm)
160x200	1 700
180x200	1 900



2 Pers.	1,5 hod	Utiahnúť CZ Utáhnout SI Zategnít HU Meghúzni HR Zategnuti RO Strângeti	Zmerať CZ Změřit SI Izmerit HU Lemérni HR Izmjeriti RO Măsurați	Zatlačiť CZ Zatlačit SI Potisnit HU Benyomni HR Pritisnuti RO Împingeți	Stlačiť CZ Zmáčknout SI Stisnit HU Megnyomni HR Stisnuti RO Apăsați	Zatlouct CZ Zatlouct SI Udarit s kladivom HU Beütni HR Zabiti RO Împingeți



SK	Na čistenie nepoužívajte abrazívne čistiace prostriedky!
CZ	K čištění nepoužívejte abrazivní čisticí prostředky!
SI	Za čiščenje ne uporabljajte abrazivnih čistilnih sredstev!
HU	Ne használjon súroló hatású tisztítószereket a tisztításhoz!
HR	Za čišćenje nemojte koristiti abrazivna sredstva za čišćenje!
RO	Nu folosiți agenți de curățare abrazivi pentru curățare!



160, 180x200


A	B (mm)			C	D
1	898	75	75	1x	1/3
2	898	75	75	1x	1/3
4	1950	200	22	1x	2/3
5	1950	200	22	1x	2/3
6	438	223	22	1x	2/3
7	438	223	22	1x	2/3
9	750	203	22	2x	2/3
10	750	203	22	2x	2/3
11	550	180	16	2x; 2x	1/3; 2/3
12	550	180	16	2x; 2x	2/3; 3/3
13	691	180	16	2x; 2x	1/3; 2/3
14	701	543	3	4x	3/3
18	448,5	113	16	1x	1/3
19	748	113	16	2x	3/3

160x200


A	B (mm)			C	D
3	1550	627	22	1x	3/3
8	1650	453	75	1x	1/3
15	1603	286,5	16	1x	3/3
16	1599	284	16	1x	1/3
17	1600	286,5	16	1x	1/3

180x200



A	B (mm)			C	D
3	1750	627	22	1x	3/3
8	1850	453	75	1x	1/3
15	1803	286,5	16	1x	3/3
16	1799	284	16	1x	1/3
17	1800	286,5	16	1x	1/3




A4 ø15x12 x28	A8 33x15 x16	B2 ø7x45 x26	B4 ø7x20 x4	B6 M8x75 x16	B7 ø7x83 x1	C1 ø8x30 x16
C3 ø8x50 x1	C6 ø10x40 x20	E3 ø30x2 x2	E8 ø20x2 x4	F20.1 R L 550 x4	F20.2 R L 550 x4	G1 14x15 x16
J3 M6x25 x2	K4 ø4x13 x24	K6 ø5x13 x24	N12 ø4x18 x12	R1 4 x1	R4 M8 x1	S1 ø17x5 x16
T1 ø7x50 x16	W2 ø7x1 x2	X10 82x42 x2	X11 70x40 x2	Y4 M8 x16	Y5 M6 x2	





160,180x200




1





16





2





3



4




5




6**7**





8



9



10



11



12

B6	M8x75 x4	C6	ø10x40 x4
----	-------------	----	--------------




13

A8 x4	33x15 x4	R4 x1	M8	Y4 x4	M8 x4
----------	-------------	----------	----	----------	----------

4x**4x**







14


B2 ø7x45 x2	B6 M8x75 x8	E3 ø30x2 x2
-------------------	-------------------	-------------------






15



A8		33x15 x8
R4		M8 x1
Y4		M8 x8

**8x****8x**



16B4
ø7x20
x4B6
M8x75
x4E8
ø20x2
x4

17**18**

19
















4x



20



A8		33x15 x4
R4		M8 x1
Y4		M8 x4




4x**4x**








21**4x****4x****4x****11****A4****12****A4****4x**

22

R1	4	T1	16
x1		ø7x50	

**23**

24**25**

26**27**

28

W2
∅7x1
x2

