


ANITA



KONDELA s.r.o.
Vojtaššákova 893
027 44 Tvrdosín
SLOVAKIA
Tel.: 00421-(0)43-45 11 111
www.kondela.sk
info@kondela.net




Nº packing	Name	a*b*c	kg
1	P1	80cmX29cmX8.6cm	11
2	P2	82cmX45.5cmX9cm	18
3	P3	58cmX29cmX8.6cm	8
4	P4	82cmX45.5cmX8.5cm	18,5
5	P5	80cmX29cmX8.6cm	11
6	P6	82cmX45.5cmX11cm	23
7	ZGORNJA VRATA	57.5cmX40.5cmX9cm	11.25
8	SPODNJA VRATA	72.5cmX40.5cmX9cm	17.25
9	PULT	81cmX61cmX8cm	24
10	OKOVJA	42cmX21.5cmX9.5cm	3

P6

A - 26		G - 10		B 3,5x16 - 32
K - 4		H - 2		D - 6
E 96mm - 3		L 400mm - 2		F - 60
1				


Nº	a*b*c	x
1	820x560x16	x2
2	368x560x16	x1
3	368x80x16	x2
4	400x84x16	x4
5	310x84x16	x4
6	396x340x3	x2
7	355x396x3	x2
8	396x428x16	x1
9	396x140x16	x2
10	100x368x16	x1

P6



 A - 42	 G - 54	 B 3,5x16 - 112
 K - 12	 H - 20	 D - 16
 E 96mm - 12	 Q - 16	 F - 150
 L 400mm - 2	 N - 6	 M 3,5x22 - 18
 M 3,5x30 - 10	 GLUE - 1	 1
	 4	

P1




P5

 <i>H - 2</i>	 <i>G - 8</i>	 <i>B 3,5x16 - 8</i>
 <i>Q - 4</i>	 <i>E 96mm - 1</i>	 <i>D - 2</i>
 <i>N - 2</i>	 <i>M 3,5x22 - 6</i>	 <i>F - 28</i>
 <i>1</i>		

<i>Nº</i>	<i>a*b*c</i>	<i>x</i>
<i>1</i>	<i>368x280x16</i>	<i>x2</i>
<i>2</i>	<i>368x264x16</i>	<i>x1</i>
<i>3</i>	<i>570x280x16</i>	<i>x2</i>
<i>4</i>	<i>298x396x3</i>	<i>x2</i>
<i>5</i>	<i>396x566x16</i>	<i>x1</i>

P5




P1

 $H - 4$	 $G - 8$	 $B\ 3,5 \times 16 - 16$
 $Q - 4$	 $E\ 96\text{mm} - 2$	 $D - 4$
 $N - 2$	 $M\ 3,5 \times 22 - 6$	 $F - 35$
 1		

N^o	$a*b*c$	x
1	768x280x16	x2
2	768x264x16	x1
3	570x280x16	x2
4	298x796x3	x2
5	396x566x16	x2

P2




P4

<i>A - 6</i>	<i>G - 10</i>	<i>B 3,5x16 - 16</i>
<i>K - 4</i>	<i>H - 4</i>	<i>D - 4</i>
<i>E 96mm - 2</i>	<i>Q - 4</i>	<i>F - 40</i>
<i>1</i>		

<i>Nº</i>	<i>a*b*c</i>	<i>x</i>
<i>1</i>	<i>820x560x16</i>	<i>x2</i>
<i>2</i>	<i>768x560x16</i>	<i>x1</i>
<i>3</i>	<i>768x80x16</i>	<i>x2</i>
<i>4</i>	<i>767x400x16</i>	<i>x1</i>
<i>5</i>	<i>355x796x3</i>	<i>x2</i>
<i>6</i>	<i>713x396x16</i>	<i>x2</i>
<i>7</i>	<i>100x768x16</i>	<i>x1</i>

P4




P2

<i>A - 6</i>		<i>G - 10</i>		<i>B 3,5x16 - 16</i>	
<i>K - 4</i>		<i>H - 4</i>		<i>D - 4</i>	
<i>E 96mm - 2</i>		<i>1</i>			

Nº	a*b*c	x
1	820x560x16	x2
2	768x560x16	x1
3	768x100x16	x2
4	713x396x16	x2
5	100x768x16	x1

P3



P3

 $H - 4$	 $G - 8$	 $B 3,5x16 - 16$
 $Q - 4$	 $E 96mm - 2$	 $D - 4$
 $N - 2$	 $M 3,5x22 - 6$	 $F - 35$
 1		

N^o	$a*b*c$	x
1	768x280x16	x2
2	768x264x16	x1
3	570x280x16	x2
4	298x796x3	x2
5	396x566x16	x2