



PANTOFAR FP-04




FP-04




A




B



C




D



E




F




x3

x2


G




H




I




J




K




L




M




N




O




P



Q




R



S



T



x3

1



x22

2




x9

3



x4

4



x24

5



x8

6




x17

7




x5

8




x32

9




x5

10




x4

11




x4

12




x4

13




x1

14




x4

15




x4

16



17



x2

