















ELARA







<p>A x24</p>  <p>M6x100mm</p>	<p>B x44</p> 	<p>C x40</p>  <p>Ø8x30mm</p>	<p>D x1</p>  <p>M6x30mm</p>	<p>E x1</p> 
<p>F x2</p> 	<p>G x80</p>  <p>Ø4x30mm</p>	<p>H x12</p> 	<p>J x12</p> 	<p>K x8</p> 
<p>L x16</p>  <p>Ø4x16mm</p>	<p>M x19</p>  <p>M6x80mm</p>	<p>N x1</p>  <p>M6x60mm</p>	<p>P x51</p> 	




02




03



06




07




08




C x16 ø8x30mm	H x12
----------------------	-----------




09




A x8 M6x100mm	B x8
P x8 	F x1




10



11



12




13




G x8





Ø4x30mm




14



15




16




J x8




P x8





17



J x4



18



19

