



















LUKOS






1




x3




2




2/5



3



Ax24



M6x20mm



Cx24



Dx1



4



Ax8



M6x20mm


Cx8




Dx1





Ex2




3/5




5






6



4/5



7



5/5

