






FRISBO 60 GU-36 1F

max. 5kg KUH.40001







KUH.10151 x2	357,5x290x16
KUH.40009	567x276x16
KUH.40012	567x276x16
KUH.60184	353x585x2,5

 A	 B	 E1	 HG	 K
8	8	8	2	2
 K24	 O	 P5	 P7	 P8
2	1	4	8-10	4






1

$\varnothing 8 \times 30 \text{ mm}$  A 8	$\varnothing 4.0 \times 30 \text{ mm}$  P8 4	 K 2
--	---	--






2









$6.4 \times 50 \text{ mm}$  B 4	 O 1	 E1 4
--	--	---

3



4



		354x596

60 GU-36

60 NAGU-36

KUH.71162



L=320mm	±7/2mm
S 1	J5 2

KUH.71162	355x596x16
------------------	-------------------


1

60 GU-36


±35/0mm	±3.5x13mm	±7/2mm
 [CD] HG	 P5	 J5
2	4	2




1.







2.







2



3




4




5

60 NAGU-36



6



7

