



FRISBO 40 G-108 1F




KUH.30008
KUH.40019



KUH.10602 x2	1073x290x16
KUH.30008 x3	366x250x16
KUH.40019 x2	367x276x16
KUH.60464	1070x385x2,5








 A 8	 B 8	 E1 8	 HG 3	 J3 12	 K 2	 O 1	 P5 6	 P7 8-10	 P8 4
------------	------------	-------------	-------------	--------------	------------	------------	-------------	----------------	-------------








1

†8x30mm  A	†4.0x30mm  P8	 K
8	4	2




2

6,4 x 50mm		
		
B	O	E1
4	1	4






3







6,4 x 50mm		
		
B	O	E1
4	1	4











4






5





6









7



8



	 Ø5mm Ø10mm		
	 0.5h	1070x396	



KUH.71405

L=160mm	M4x27mm
	
S	U8
1	2

KUH.71405	1070x396x19
-----------	-------------


1

LEFT



RIGHT



KUH.71405





KUH.71405




2

 HG 3	 P5 6
---	---



3

L=160mm	M4x27mm
	
S	U8
1	2



KUH.71405

