


1	608	355	16	1	1/5	1/4	1/5	1/5
30	608	355	16	1	1/5	1/4	1/5	1/5
50	568	335	16	1	1/5	1/4	1/5	1/5
71	566	325	16	3	4/5	4/4	-	4/5
72	564	325	6	3	-	-	5/5	-
91	1950	335	16	1	3/5	3/4	3/5	3/5
92	1950	335	16	1	3/5	3/4	3/5	3/5
156	596	191	19	2	3/5	3/4	3/5	3/5
176	320	120	16	2	3/5	3/4	3/5	3/5
177	320	120	16	2	3/5	3/4	3/5	3/5
186	510	120	16	2	1/5	1/4	1/5	1/5
201	320	70	16	2	3/5	3/4	3/5	3/5
206	1556	596	19	1	4/5	-	-	-
226	1556	596	19	1	-	-	4/5	-
232	1556	596	19	1	-	-	4/5	-
241	210	370	80	1	2/5	2/4	2/5	2/5
242	210	370	80	1	2/5	2/4	2/5	2/5
251	690	80	19	1	3/5	3/4	3/5	3/5
266	396	80	19	1	3/5	3/4	3/5	3/5
267	396	80	19	1	3/5	3/4	3/5	3/5
281	596	404	2,5	1	4/5	4/4	4/5	4/5
282	1574	596	2,5	1	4/5	4/4	4/5	4/5
311	540	325	2,5	2	1/5	1/4	1/5	1/5



<b>A1</b> 22	<b>C1</b> 8x35 22	<b>A2</b> 22	<b>G</b> 1,5x26 62
<b>D1</b> 4(0*,4**,4***)	<b>S5</b> 12	<b>R24</b> 7x50 8	<b>I</b> 1
<b>E1</b> 4(0*,4**,4***)	<b>P4</b> 12	<b>Q</b> 6(4*,6**,6***)	<b>N1</b> 6
<b>Ri2</b> 12(0*,8**,12***) 3,5x16	<b>R9</b> 4x25	<b>R23</b> 6 6,3x13	<b>S11</b> 8(16*)
<b>Z10</b> 300	<b>H18</b> 2 3(2*,3**,3***)	<b>R3</b> 3x20	<b>R10</b> 22 4x30
<b>R27</b> 5,0x13 20	<b>M1</b> M4x12	<b>M12</b> 4 M4x25	<b>R12</b> 4 4x40
<b>U8</b> 120° 2	<b>R30</b> 2,9x9,5 4	<b>S6</b> 1	<b>B5</b> 10x50 1
			<b>S3</b> 2

