





R3 SA







No	L[mm]	W[mm]	H[mm]	PCS	BOX
103	1940	400	15	1	2/3
104	1940	400	15	1	2/3
201	902	430	36	1	1/3
301	850	400	15	1	2/3
302	850	400	15	1	2/3
303	850	400	15	3	1/3
401	849	60	15	1	1/3
5111	1915	438	2,5	2	2/3
601	1940	50	22	2	2/3







A1 x20 Ø8x35mm	B1 x20 Ø5x38mm	C1 x20 Ø15x12mm	E1 x12 Ø5x16mm	G1 x44 26mm
H x1 1915mm	J1 x16 Ø21mm	T4 x2 75x28x16 mm	W2 x4 Ø3,5x16mm	W5 x2 Ø4x30mm
Y5 x7 Ø15x20mm				






1



2




3




4

A1 x 8







Ø8x35mm






C1 x 8





Ø15x12mm





5





6





7







8



9






10




A=B






11






12







13






14













15



16



17



ca.100 mm

ca.100 mm

