









# Montážny návod - MALTO CT-024



Č.	Ks		
1	12		40mm
2	6		45mm
3	1		4mm