












W40S




<p>A x8</p>  <p>Ø8x35mm</p>	<p>B x8</p> 	<p>C x8</p>  <p>Ø15x12mm</p>	<p>E x8</p> 
<p>G x40</p> 	<p>M x1</p> 	<p>W2 x4</p>  <p>Ø3,5x16</p>	
<p>Zc x2</p>  <p>Zc-1 Zc-2</p>			



1




2




3



4



5



6

